STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291

Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

1.	Report Time Period: From (mo./yr.) /-2003 To (mo./yr.) /-2004		
2.	DOGM File Number (Mine No): \$17/00/46		
3.	Mine Name: MILLA' MARTINIQUE		
4.	Mineral(s) Mined (or permitted to mine): GOLD - Precious METALS		
5.	Type of mine ✓ Surface Mine or ☐ Underground Mine		
6.	Legal Description (Location of Lands Affected):		
	1/4,1/4, <u>\$\omega\$</u> 1/4, Section <u>25</u> , Township <u>315</u> , Range <u> E</u>		
	1/4,1/4,1/4, Section, Township, Range		
	1/4,1/4,1/4, Section, Township, Range		
Nar	ne of Operator or Company: MARTINIQUE MINING CORPORATION		
8.	Permanent Street Address: 2784 JEFFERSON AVE.		
	City, State, Zip: Ogten Utah 84403		
	Phone: 801-393-5307 Fax: 801-393-5329		
9.	Company Representative (or designated operator):		
	Name: Kim E. Wilson		
	Title: President		
	Business Address: P-D. Box 1688		
	City, State, Zip: CARLIN NEUADA 898ZZ		
	Phone: 775-754-2188 Fax: same		
	Please check if any of the above information has changed since previous year.		
Min	Mining and Reclamation		
1	Was there any mine related activity during the past year? Yes ☒ No □		
1.			
2.	If no - what was the last year of activity?		
3.	If yes - how much ore or mineral was mined? SAMPLES RECEIVED		
	(IAN 0. 7.200)		
	JAN 0 7 2004		
	DIV. OF OIL, GAS & MINING		

4.	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.	
	Mill EQUIPMENT Maint Repair - SLOPE Groom!	U
	AND PILOT WILL DIS ASSEMBLY AND RELAMATION.	
	Removal of SKID MOUNT STRUCTURE OFFICE BUILDIN	30
	Re-SLOPE AND SOIL excavation work	
5.	How much additional acreage was disturbed during the past year?	
6.	How much acreage was reclaimed during the past year? 43 Acre	
7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results. DISASSEMBY OF MILL PARTS AND TEMP. STORAGE for Remove-all off site. Re-slope AND Grooming of Area-Area Clean-up-Pulled Equiponto small area for transport LOADING.	
8.	What is the total disturbed acreage of entire project at years end? ZO acre	
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year. Removal of equipment and clean-up of entire site for Fall final inspection	
NOTE:	Section III., "Additional Information" applies only to <u>large mining operations</u> .	
III. Additional	<u>Information - R647-4-121.2 and .3</u>	
1.	The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.	
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.	
IV. <u>Signature</u>	<u>Requirement</u>	
I here	by certify that the foregoing is true and correct.	
	Name (Typed or Print): Kim 2. Wilson	
	Title of Operator: President	
	Signature of Operator:	
	Name (Typed or Print): Title of Operator: Signature of Operator: Date: **Title of Operator: **Title of Operato	
jb o:\forms\reports\MR-A	AR .	